MAX EXTREME V2 SOFTWARE REPROGRAMMING INSTRUCTIONS

IMPORTANT: throughout this procedure the Max MUST be disconnected from the power supply.

1) Connect the PicKit 2 programmer to the PC using the supplied USB cable.

2) Start your PC and save the new Max software program 'HEX' file (from WON) to your desk top.

3) Connect the Max 2 to the programmer via the mini USB socket using the supplied short cable.

4) Open up the PIC kit 2 program.

5) Click on the 'Auto Import HEX' button near the bottom right.

6) Browse to the HEX file saved on the desktop and select it.

7) The unit will program and take approx 10 seconds to do so. Once it's finished the display in the top left of the screen will turn green.

8) Disconnect the reprogramming cable.